honeywell.com/PSSsoftware-downloads

sps.honeywell.com

www.hsmpats.com

24V ⎓ 2.5A

Disclaimer
Honeywell International Inc. (“HII”) reserves the right to make changes in specifications and other information contained in this document without prior notice, and the reader should in all cases consult HII to determine whether any such changes have been made. HII makes no representation or warranties regarding the information provided in this publication. HII shall not be liable for technical or editorial errors or omissions contained herein; nor for incidental or consequential damages resulting from the furnishing, performance, or use of this material. HII disclaims all responsibility for the selection and use of software and/or hardware to achieve intended results.
This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be photocopied, reproduced, or translated into another language without the prior written consent of HII.

PC42E-T-ML-QS-01 REV-B 09/23

Honeywell

PC42E-T

DESKTOP PRINTER

QUICK START GUIDE

打印机快速入门指南
印表機快速入門指南
Guide de démarrage de l’ imprimante haute performance
Kurzanleitung für Hochleistungsdrucker
Panduan Cepat Printer Berkemampuan Tinggi
Guida rapida per stampante ad alte prestazioni
고성능 프린터 빠른 시작 안내서
Guia de iniciação rápida da impressora de alto desempenho
Краткое руководство по эксплуатации высокопроизводительного принтера
Guía de comienzo rápido para la impresora de alto rendimiento
Yüksek Performanslı Yazıcı Hızlı Başlama Kılavuzu

Copyright © 2023 Honeywell Group of Companies. All rights reserved.

PC42E-T

MEDIA LOADING



RIBBON LOADING



PAUSE/CANCEL PRINTING

ON BATCH JOB MODE:

CLICK FEED BUTTON
TO **PAUSE** PRINTING

PRESS AND HOLD
FEED BUTTON
TO **CANCEL** PRINTING



SENSOR ADJUSTMENT