


Connectivity Lock - Steel Cable Tether

Product Diagram (CONNLOCKPK)



| Part | Function |
|----------------------|---|
| 1 Steel Cable Tether | • Tether A/V Cables to A/V Adapters |
| 2 Aluminum Ferrule | • Create a loop by routing the Steel Cable Tether through each opening • Crimp to secure the Steel Cable Tether loop |
| 3 Heat Shrink Tubing | • Shrink around the crimped Aluminum Ferrules |

Requirements

- Swaging Tool x 1
- (Optional) Heat Gun x 1
- (Optional) Wire Cable Cutter x 1

For the latest requirements please visit: www.startech.com/CONNLOCKPK.

Installation

1. (Optional) Thread the **Heat Shrink Tubing** onto the center of the **Steel Cable Tether**.

*Note: This step is necessary if you plan to utilize the **Heat Shrink Tubing**.*

2. Thread the **Aluminum Ferrules** onto each end of the **Steel Cable Tether**.
3. Wrap one end of the **Steel Cable Tether** around the **A/V Cable**.

4. Route the working end of the **Steel Cable Tether** back into the second hole in the **Aluminum Steel Ferrule**.
5. Cinch the **Steel Cable Tether** until it fits snugly around the **A/V Cable**.

*Note: Do not cinch the **Steel Cable Tether** down all the way. Cinch the **Steel Cable Tether** until it is no longer possible to slip the loop over the connectors of the **AV Cable**.*

6. Crimp the **Aluminum Steel Ferrule** in the appropriate setting of a **Swaging Tool**. (Figure 1)

*Note: It may be necessary to crimp the **Aluminum Steel Ferrule** a few times to create a strong and circular shaped crimp.*

Figure 1



7. Wrap the other end of the **Steel Cable Tether** around the cable portion of the **A/V Adapter**.

- Repeat steps 4 to 6 to secure the **Connectivity Lock** to the cable portion of the **A/V Adapter**. (Figure 2)

Figure 2



- (Optional) Slide the **Heat Shrink Tubing** over the crimped **Aluminum Ferrules**.
- (Optional) Apply heat to the **Heat Shrink Tubing** using a **Heat Gun**. Always keep the **Heat Gun** moving to ensure the heat is evenly distributed over the **Heat Shrink Tubing**. (Figure 3)

Note: Apply just enough heat to shrink the **Heat Shrink Tubing**. Excessive heat will melt the nylon sheath that covers the **Steel Cable Tether**.

Figure 3



Removal

- Cut both ends of the **Steel Cable Tether** using a **Wire Cable Cutter**.

Note: Ensure the cut is made close to the **Aluminum Steel Ferrule** to prevent any damage to the **Cables**.

Use of Trademarks, Registered Trademarks, and other Protected Names and Symbols

This manual may make reference to trademarks, registered trademarks, and other protected names and/or symbols of third-party companies not related in any way to StarTech.com. Where they occur these references are for illustrative purposes only and do not represent an endorsement of a product or service by StarTech.com, or an endorsement of the product(s) to which this manual applies by the third-party company in question. StarTech.com hereby acknowledges that all trademarks, registered trademarks, service marks, and other protected names and/or symbols contained in this manual and related documents are the property of their respective holders.

Warranty Information

This product is backed by a one-year warranty.

For further information on product warranty terms and conditions, please refer to www.startech.com/warranty.

Limitation of Liability

In no event shall the liability of StarTech.com Ltd. and StarTech.com USA LLP (or their officers, directors, employees or agents) for any damages (whether direct or indirect, special, punitive, incidental, consequential, or otherwise), loss of profits, loss of business, or any pecuniary loss, arising out of or related to the use of the product exceed the actual price paid for the product. Some states do not allow the exclusion or limitation of incidental or consequential damages. If such laws apply, the limitations or exclusions contained in this statement may not apply to you.

| | | | |
|--|--|---|--|
| StarTech.com Ltd. 45 Artisans Cres London, Ontario N5V 5E9 Canada | StarTech.com LLP 2500 Creekside Parkwy Lockbourne, Ohio 43137 U.S.A. | StarTech.com Ltd. Unit B, Pinnacle 15 Gowerton Rd, Brackmills Northampton NN4 7BW United Kingdom | FR: fr.startech.com DE: de.startech.com ES: es.startech.com NL: nl.startech.com IT: it.startech.com JP: jp.startech.com |
|--|--|---|--|