



CS60 series Technical Accessory Guide







NOTE: This document is only for general reference. Solutions Pathway and related PMBs should be used for product availability, pricing, and final solution selection.





* Zebra does not endorse or specifically recommend any **third-party products, accessories, or hardware**. ZEBRA DISCLAIMS ANY AND ALL LIABILITY, INCLUDING ANY EXPRESS OR IMPLIED WARRANTIES, WHETHER ORAL OR WRITTEN, FOR SUCH THIRD PARTY PRODUCTS, ACCESSORIES, OR HARDWARE. THE CUSTOMER ACKNOWLEDGES THAT NO REPRESENTATION HAS BEEN MADE BY ZEBRA AS TO THE FITNESS OF THE THIRD-PARTY PRODUCTS, ACCESSORIES, OR HARDWARE FOR THE CUSTOMER'S INTENDED PURPOSE.

Cradles/Charging


Part Number	Description	Notes	Required Items
CR6080-SC100F4WW CR6080-SC100F4CN (for China only)	 <p>Single Slot Device + Spare Battery Charge/Communication Cradle</p>	<ul style="list-style-type: none"> ! Cradle will charge CS60 and provide communications. ! Also charges one spare battery. ! Uses inductive charging for CS60 unit ! Device communicates to cradle via Bluetooth. ! Cradle includes pager button to locate CS60 unit if lost. ! Cradle also includes beeper which can be enabled to sound for Virtual Tether events. ! Includes cap to cover spare battery charging slot if spare battery charging is not needed. 	<ul style="list-style-type: none"> ! USB-C to USB-A cable (CBL-CS6-S07-04) To power cradle without PC connection: <ul style="list-style-type: none"> ! USB Power Supply (PWR-WUA5V6W0WWW)
CR6080-SC400F4WW	 <p>4-Slot Charge-Only Cradle KIT</p>	<ul style="list-style-type: none"> ! Cradle charges four CS60 units simultaneously. ! Does not charge spare batteries. ! Uses inductive charging. ! Uses Zebra ShareCradle design ! Kit includes: <ul style="list-style-type: none"> - 4-Slot Charge-Only Cradle Adapter Cup + ShareCradle base (CR6080-SC400F4WWNS) - Power Supply (PWR-BGA12V50W0WWW) - DC Line Cord (CBL-DC-388A1-01) 	<ul style="list-style-type: none"> AC Line Cord (23844-00-00R or country specific cord)

CR6080-SA40004WW		4-Slot Charge-Only Cradle Adapter Cup	<p>! Cradle charges four CS60 units simultaneously.</p> <p>! Does not charge spare batteries.</p> <p>! Uses inductive charging.</p> <p>! Allows existing Single or Multi-Slot ShareCradle to be modified to support CS60. Existing cradle cup can be removed from a ShareCradle and replaced with this CS60 cup.</p>	! Existing Single or Multi-Slot ShareCradle (typically from a mobile computing product)
various (3rd party) *		Qi Charging Pad	<p>! Allows CS60 unit to be charged.</p> <p>! Just place the scanner on top of the pad</p>	
CR6080-BC40004WW		4-Slot Spare Battery Charger KIT	<p>! Cradle charges four CS60 batteries simultaneously.</p> <p>! Uses Zebra ShareCradle design</p> <p>! Kit includes:</p> <ul style="list-style-type: none"> - 4-Slot Spare Battery Cradle Adapter Cup + ShareCradle base (CR6080-BC40004WWNS) - Power Supply (PWR-BGA12V50W0WW) - DC Line Cord (CBL-DC-388A1-01) 	AC Line Cord (23844-00-00R or country specific cord)
CR6080-BA40004WW		4-Slot Spare Battery Charger Cup	<p>! Cradle charges four CS60 batteries simultaneously.</p> <p>! Allows existing Single or Multi-Slot ShareCradle to be modified to support CS60. Existing cradle cup can be removed from a ShareCradle and replaced with this CS60 cup.</p>	! Existing Single or Multi-Slot ShareCradle (typically from a mobile computing product)

STND-GS0060C-04		Gooseneck Stand - Standard Base (SR Black color)	! Scanner enters into presentation mode when inserted into cup.	
STND-GS0060C-0B		Gooseneck Stand - Standard Base (Healthcare White color)	! Scanner enters into presentation mode when inserted into cup.	
STND-WS0060C-04		Gooseneck Stand - Weighted Base (SR Black color)	! Scanner enters into presentation mode when inserted into cup. ! Stand features a weighted base to prevent tip-over.	
STND-WS0060C-0B		Gooseneck Stand - Weighted Base (Healthcare White color)	! Scanner enters into presentation mode when inserted into cup. ! Stand features a weighted base to prevent tip-over.	

CVTR-U70060C-04		USB Converter Cable - Black	! Cable converts CS60 to a corded scanner. Replaces battery. ! 7 ft. length, straight cable ! USB-A connector	
CVTR-U70060C-0B		USB Converter Cable - White	! Cable converts CS60 to a corded scanner. Replaces battery. ! 7 ft. length, straight cable ! USB-A connector	
CBL-CS6-S07-04		USB-C to USB-A Cable for Cradles, Black color	! Cable connects Single Slot Device + Battery Charge/Communication Cradle (CR6080-SC100F4WW or CR6080-SC100F4CN) to host. ! 7 ft. length, straight cable ! USB-A to USB-C connector	
CBL-CS6-S07-0B		USB-C to USB-A Cable for Cradles, White color	! Cable connects Healthcare Cart Mountable Device Communication Presentation Charge Cradle (CR6080-PC100FBWW or CR6080-PC100FBCN) to host. ! 7 ft. length, straight cable ! USB-A to USB-C connector	

Power Cords

Part Number	Picture	Description	Notes	Required Items
PWR-WUA5V6W0WWW		USB Power Supply	! Used to charge CS60 in Single Slot Charge/Communication Cradle (CR6080-SC100F4WW) without a PC. ! Includes four international plugs for use in US, UK, EU, and AU. Additional plugs can be purchased separately for other countries. ! 5.2V, 1.2A, 6W output ! Provides US DOE Level VI compliance for power efficiency	

