

# HP original long-life consumables are specifically designed for and tested with your HP device



## Maintain productivity

Get optimal print quality and keep your printer or multifunction product (MFP) up and running smoothly with HP original long life consumables (LLCs), including fuser kits, image transfer kits, print image drums, toner collection units (TCU), and automatic document feeder (ADF) maintenance kits. When your printer prompts you that it needs maintenance, simply pull out the kit and replace parts as needed.

## Fuser kit

The fusing assembly in your HP device bonds toner to paper through a combination of heat and pressure. Replacement of your device's fusing assembly is simple with the HP fuser maintenance kit.

## Transfer kit

Although your HP device's original transfer belt and drum are built to last, they wear down over time and may require replacement. An HP image transfer kit has everything you need to ensure your device keeps delivering optimal print quality.

## ADF maintenance kit

Your HP device's ADF makes scanning and copying documents fast and simple. Stay productive and keep your ADF working properly with an HP ADF maintenance kit.

## Print image drums

Maintain sharp, crisp and clean text and graphics with an imaging drum designed to work seamlessly with HP LaserJet toner cartridges and advanced toner formulation. Use Original HP supplies for professional-quality results.

## Toner collection unit

HP utilizes several different methods to collect unused toner, paper fibers, and dust in the imaging system. Some TCUs are built into our all in one cartridges; others are physically incorporated into a long life consumable or packaged with a maintenance kit.

The TCU is an easy-to-replace, high-yield HP supply designed to reduce user-intervention rates. On many devices, the printer control panel provides a proactive alert when the TCU is approaching its end of life and you need to order a replacement.

## Easy recycling

After installing the replacement kit in your device, easily recycle your old parts for free through the HP Planet Partners Program.<sup>1</sup>

<sup>1</sup> Visit [hp.com/hpinfo/globalcitizenship/environment/recycling/product-recycling.html](https://www.hp.com/hpinfo/globalcitizenship/environment/recycling/product-recycling.html) for more information on how to recycle parts through the HP Planet Partners Program.

# HP original long-life consumables keep your device running at peak efficiency with high-quality output



## Paper Handling and finishing options HP monochrome LaserJet printers

### Printers

Devices and LLCs	Part number	Page yield
<b>M601/M602/M603</b>		
110-volt fuser kit	CF064A	225K
220-volt fuser kit	CF065A	225K
<b>M604/M605/M606</b>		
110-volt maintenance kit	F2G76A	225K
220V-volt maintenance kit	F2G77A	225K
<b>M712</b>		
110-volt maintenance fuser kit	CF249A	200K
220-volt maintenance fuser kit	CF254A	200K
<b>M806</b>		
110-volt maintenance fuser Kit	C2H67A	200K
220-volt maintenance fuser Kit	C2H57A	200K
<b>P4014/P4015/P4515</b>		
110-volt fuser kit	CB388A	225K
220-volt fuser kit	CB389A	225K
<b>4100</b>		
110-volt fuser kit	C8057A	200K
220-volt fuser kit	C8058A	200K
<b>4200</b>		
110-volt fuser kit	Q2429A <sup>3</sup>	200K
220-volt fuser kit	Q2430A <sup>3</sup>	200K
<b>4250/4350</b>		
110-volt fuser kit	Q5421A	200K
220-volt fuser kit	Q5422A	200K
<b>4300</b>		
110-volt fuser kit	Q2436A	200K
220-volt fuser kit	Q2437A	200K

### Printers

Devices and LLCs	Part number	Page yield
<b>5000</b>		
220-volt fuser kit	C7854A <sup>3</sup>	150K
<b>8100/8150</b>		
110-volt fuser kit	C3914A <sup>3</sup>	350K
220-volt fuser kit	C3915A	350K
<b>9000/9040/9050</b>		
110-volt fuser kit	C9152A	350K
220-volt fuser kit	C9153A	350K

### MFP's

Devices and LLCs	Part number	Page yield
<b>M525</b>		
ADF Roller Replacement Kit	L2718A	100K <sup>4</sup>
<b>M527</b>		
ADF Roller Replacement Kit	B5L52A	75,000
<b>M630</b>		
110-volt maintenance kit	B3M77A	225K <sup>4</sup>
220-volt maintenance kit	B3M78A	225K <sup>4</sup>
ADF roller replacement kit	L2718A	100K <sup>4</sup>
<b>M830</b>		
110-volt fuser kit	C2H67A	200K <sup>4</sup>
220-volt fuser kit	C2H57A	200K <sup>4</sup>
ADF maintenance kit	C1P70A	100K <sup>2</sup>
<b>4345/M4345</b>		
110-volt fuser kit	Q5998A	225K <sup>4</sup>
220-volt fuser kit	Q5999A	225K <sup>4</sup>
ADF maintenance kit	Q5997A	90K <sup>4</sup>

**MFP's**

Devices and LLCs	Part number	Page yield
<b>M4555</b>		
110-volt fuser kit	CE731A	225K <sup>4</sup>
220-volt fuser kit	CE732A	225K <sup>4</sup>
ADF maintenance kit	CE248A	90K <sup>2</sup>
<b>M5025/M5035</b>		
110-volt fuser kit	Q7832A	200K <sup>4</sup>
220-volt fuser kit	Q7833A	200K <sup>4</sup>
ADF maintenance kit	Q7842A	60K <sup>2</sup>
<b>9000/9040/9050/M9040/M9050</b>		
110-volt fuser kit	C9152A	350K <sup>4</sup>
220-volt fuser kit	C9153A	350K <sup>4</sup>

## HP color LaserJets

**Printers**

Devices and LLCs	Part number	Page yield
<b>CP1025</b>		
Print Drum	CE314A	14K black / 7K color <sup>5</sup>
<b>M551</b>		
110-volt fuser kit	CE484A	150K
220-volt fuser kit	CE506A	150K
<b>M552</b>		
110v Fuser Kit	B5L35A	150K
220v Fuser Kit	B5L36A	150K
Toner Collection Unit	B5L37A	54K
<b>M553</b>		
110v Fuser Kit	B5L35A	150K
220v Fuser Kit	B5L36A	150K
Toner Collection Unit	B5L37A	54K
<b>M855</b>		
Black Image Drum	CF358A	30K <sup>5</sup>
Cyan Image Drum	CF359A	30K <sup>5</sup>
Yellow Image Drum	CF364A	30K <sup>5</sup>
Magenta Image Drum	CF365A	30K <sup>5</sup>
110-volt fuser kit	C1N54A	100K
220-volt fuser kit	C1N58A	100K
Image transfer kit	D7H14A	Yield = 150K
<b>1500</b>		
Print Drum	C9704A	20K black/5K color <sup>5</sup>
<b>2500</b>		
Print Drum	C9704A	20K black/5K color <sup>5</sup>
<b>2550</b>		
Print Drum	Q3964A	20K black/5K color <sup>5</sup>
Toner collection unit	CE254A	36K
<b>3500</b>		
110-volt fuser kit	Q3655A	60K <sup>4</sup>
220-volt fuser kit	Q3656A	60K <sup>4</sup>
Image transfer kit	Q3658A	60K <sup>4</sup>

**Printers**

Devices and LLCs	Part number	Page yield
<b>CP3520/CP3525</b>		
110-volt fuser kit	CE484A	150K <sup>4</sup>
220-volt fuser kit	CE506A	150K <sup>4</sup>
Toner collection unit	CE254A	36K
<b>3550/3700</b>		
110-volt fuser kit	Q3655A	75K
220-volt fuser kit	Q3656A	75K
Image transfer kit	Q3658A	75K
<b>CP4005</b>		
110-volt fuser kit	Q7502A	125K
220-volt fuser kit	Q7503A	125K
Image transfer kit	Q7504A	100K
<b>CP4025/CP4525</b>		
110-volt fuser kit	CE246A	150K
220-volt fuser kit	CE247A	150K
Image transfer kit	CE249A	150K
Toner collection unit	CE265A	36K
<b>4600</b>		
110-volt fuser kit	C9725A	150K
220-volt fuser kit	C9726A	150K
Image transfer kit	Q3675A	120K
<b>4650</b>		
110-volt fuser kit	Q3676A	150K
220-volt fuser kit	Q3677A	150K
Image transfer kit	Q3675A	120K
<b>4700</b>		
110-volt fuser kit	Q7502A	150K
220-volt fuser kit	Q7503A	150K
Image transfer kit	Q7504A	120K
<b>5500</b>		
110-volt fuser kit	C9735A	150K
220-volt fuser kit	C9736A	150K

**Printers**

Devices and LLCs	Part number	Page yield
Image transfer kit	C9734B	150K

**MFP's**

Devices and LLCs	Part number	Page yield
------------------	-------------	------------

**M570**

110-volt fuser kit	CE484A	150K <sup>4</sup>
220-volt fuser kit	CE506A	150K <sup>4</sup>
Toner collection unit	CE254A	36K

**M575**

110-volt fuser kit	CE484A	150K <sup>4</sup>
220-volt fuser kit	CE506A	150K <sup>4</sup>
Toner collection unit	CE254A	36K
ADF Roller Replacement Kit	L2718A	100K <sup>4</sup>

**M577**

ADF Roller Replacement Kit	B5L52A	75,000
110v Fuser Kit	B5L35A	150,000
220v Fuser Kit	B5L36A	150,000
Toner Collection Unit	B5L37A	54,000

**M775**

ADF Roller Replacement Kit	L2718A	100K <sup>4</sup>
Toner collection unit	CE980A	150K
110-volt image fuser kit	CE514A	150K <sup>4</sup>
220-volt image fuser kit	CE515A	150K <sup>4</sup>
Image transfer kit	CE516A	150K <sup>4</sup>

**M880**

Black Image Drum	CF358A	30K <sup>5</sup>
Cyan Image Drum	CF359A	30K <sup>5</sup>
Yellow Image Drum	CF364A	30K <sup>5</sup>
Magenta Image Drum	CF365A	30K <sup>5</sup>
110-volt fuser kit	C1N54A	100K <sup>4</sup>
220-volt fuser kit	C1N58A	100K <sup>4</sup>
Image transfer kit	D7H14A	150k <sup>4</sup>
ADF Roller Replacement Kit	C1P70A	100K <sup>4</sup>

**2820/2840**

Print Drum	Q3964A	20K black/5K color <sup>5</sup>
------------	--------	---------------------------------

**CM3530**

110-volt fuser kit	CE484A	150K <sup>4</sup>
220-volt fuser kit	CE506A	150K <sup>4</sup>
Toner collection unit	CE254A	36K

**CM4540**

110-volt fuser kit	CE246A	150K <sup>4</sup>
220-volt fuser kit	CE247A	150K <sup>4</sup>
ADF maintenance kit	CE248A	90K <sup>2</sup>
Image transfer kit	CE249A	150K <sup>4</sup>
Toner collection unit	CE265A	36K

**MFP's**

Devices and LLCs	Part number	Page yield
------------------	-------------	------------

**4730**

110-volt fuser kit	Q7502A	150K <sup>4</sup>
220-volt fuser kit	Q7503A	150K <sup>4</sup>
ADF maintenance kit	Q5997A	90K <sup>2</sup>
Image transfer kit	Q7504A	120K <sup>4</sup>

**CM6030/CM6040**

110-volt fuser kit	CB457A	100K <sup>4</sup>
220-volt fuser kit	CB458A	100K <sup>4</sup>
Image transfer kit	CB463A	150K <sup>4</sup>
Roller kit	CB459A	150K
Black Image Drum	CB384A	23K <sup>5</sup>
Cyan Image Drum	CB385A	23K <sup>5</sup>
Yellow Image Drum	CB386A	23K <sup>5</sup>
Magenta Image Drum	CB387A	23K <sup>5</sup>

**9500**

Black Image Drum	C8560A	40K <sup>5</sup>
Cyan Image Drum	C8561A	40K <sup>5</sup>
Yellow Image Drum	C8562A	40K <sup>5</sup>
Magenta Image Drum	C8563A	40K <sup>5</sup>
110-volt/220-volt fuser kit	C8556A	100K <sup>4</sup>
Image cleaning kit	C8554A	50K <sup>4</sup>
Image transfer kit	C8555A	200K <sup>4</sup>

**CP5525**

110-volt fuser kit	CE977A	150K <sup>4</sup>
220-volt fuser kit	CE978A	150K <sup>4</sup>
Toner collection unit	CE980A	150K <sup>4</sup>

**MFP's**

Devices and LLCs	Part number	Page yield
<b>5550</b>		
110-volt fuser kit	Q3984A	150K <sup>4</sup>
220-volt fuser kit	Q3985A	150K <sup>4</sup>
Image transfer kit	C9734B	120K <sup>4</sup>
<b>CP6015</b>		
Black Image Drum	CB384A	23K <sup>5</sup>
Cyan Image Drum	CB385A	23K <sup>5</sup>
Yellow Image Drum	CB386A	23K <sup>5</sup>
Magenta Image Drum	CB387A	23K <sup>5</sup>
110-volt fuser kit	CB457A	100K <sup>4</sup>
220-volt fuser kit	CB458A	100K <sup>4</sup>
Image transfer kit	CB463A	150K <sup>4</sup>
Roller kit	CB459A	150K

**HP scanners & digital sender**

Devices and LLCs	Part number	Page yield
<b>Scanjet 7500</b>		
ADF Roller Replacement Kit	L2718A	100K <sup>4</sup>
<b>Scanjet 8500</b>		
ADF Roller Replacement Kit	L2718A	100K <sup>4</sup>
<b>9250c Digital Sender</b>		
ADF maintenance kit (pkg of 3 Mylar sheets)	Q6496A	90K <sup>2</sup>

<sup>2</sup> Not available in Europe, Middle East, or Africa.

<sup>3</sup> Stated yield is based on 5% coverage and may vary based on coverage and media type used.

<sup>4</sup> Scans through ADF.

<sup>5</sup> Actual yields vary considerably based on images printed and other factors. For more information, visit [hp.com/go/learnaboutsupplies](http://hp.com/go/learnaboutsupplies).

**Learn more at**  
[hp.com](http://hp.com)

**Sign up for updates**  
[hp.com/go/getupdated](http://hp.com/go/getupdated)

